

Published based on [AIRES Boeing 737 Crashed in Colombia](#)

AIRES Boeing 737 Crashed in Colombia

An AIRES Colombia Boeing 737-73V (HK-4682) crashed on landing today at San Andres Island-Gustavo Rojas Pinilla Airport (ADZ), Colombia. One passenger died, more than 100 were injured. Flight 8250 was bound from Bogotá to San Andres Island. According to early reports the airplane may have been hit by a lightning bolt during landing on runway 06. The engines separated from the plane, it crashed on the runway and broke into three sections. Boeing is sending a team to provide technical support to the Colombia DJAC to assist in the agency's investigation of the accident, at the invitation of the Colombian authorities.

Video by CNN

Video by elespectador

You can also find this article published on [AIRES Boeing 737 Crashed in Colombia](#), and on the tag pages [aires colombia](#), [Boeing](#), [Gustavo](#), [gustavo rojas pinilla](#), [HK](#), [san andres island](#).